

MULTI-SURFACE CERAMIC CLEARCOAT

PURE AIR COATING

You will need:

Hot water pressure washer

Fan tip on wand

Battery leaf blower

Chemical tank or backpack sprayer

SIMIX Multi-Surface Cleaner/Degreaser/Sanitizer

SIMIX Multi-Surface Ceramic Clearcoat

Distilled or RO water (for coating)

Clean & Coat Asphalt Shingle and Barrel Tile Rooftops

INSTRUCTIONS

Clean with **SIMIX Multi-Surface Cleaner/Degreaser/Sanitizer**

Step 1: Clean debris off roof with pressure washer or leaf blower.

Step 2: Dissolve **SIMIX Multi-Surface Cleaner/Degreaser/Sanitizer** in hot water. Use 1 large scoop of powder per gallon of water. In Chemical tank make sure solution sprayed on roof is 4 ounces per gallon or equivalent.

Step 3: Immediately apply the solution. Rooftop should be completely soaked.

Step 4: Allow to dwell for 20 minutes.

Step 5: Rinse off with pressure washer. Repeat if needed until roof is visibly clean.

Step 6: Let roof visibly dry before applying **SIMIX Multi-Surface Ceramic Clearcoat**.

Coat the Roof

Prepare **SIMIX Multi-Surface Ceramic Clearcoat**. Refer to **Mixing/Dilution chart** (sheet).

Check temperature and consult mixing chart for proper amounts.

Step 1: Spray coating on to dry roof.

Step 2: Let coating visibly dry.

Step 3: Add 3 more coats. Always let coating visibly dry between coats.

Roofs surfaces	Asphalt Shingle, Barrel Tile (minimum 4 coats)		
Surface Temperature	45° - 99°F	100° - 120°F (40% humidity)	100° - 120°F (less than 35% humidity)
SIMIX	1 Part	1 Part	1 Part
Distilled or RO water	6 Parts	9 Parts	14 Parts
Coverage/per mixed gal.	600 -1200 sq. ft.	500 -1000 sq. ft.	400 - 800 sq. ft.

Coverage rates will vary based on type of surface, porosity, ambient temperature, surface temperature and humidity.

